


TAKE FROM MISSION 146 COMPLETE LOSS. CAMERA OPERATED 100 PER CENT; HOWEVER PROCESSING INDICATES CAUSE TO BE OIL ON WINDOWS. INITIAL ANALYSIS THIS FROM HEATER BLOWER MOTOR.

END OF MESSAGE



Pa